


DIMENSIONS(mm)

Outline details: Connector version

Connector wiring;

- Pin 1 -+ve supply
- Pin 3 --ve supply
- Pin 2 -+ve signal
- Pin 4 -Earth



HOW TO ORDER

P- 500A - A - A - B - 1 - 1

Range(kg/cm2)		
0 - 10	mmH2O	A
0 - ± 10	mmH2O	B
0 - 25	mmH2O	C
0 - ± 25	mmH2O	D
0 - 50	mmH2O	E
0 - ± 50	mmH2O	F
0 - 100	mmH2O	G
0 - 250	mmH2O	H
0 - 500	mmH2O	I
0 - 1000	mmH2O	J
0 - 2000	mmH2O	K
0 - 5000	mmH2O	L
0 ~ 1		M
0 ~ 2		N
0 ~ 4		O
0 ~ 6		P
0 ~ 10		Q
OTHER RANGES		V

Output Signal		
1 ..	4 ~ 20	mA
2 ..	1 ~ 5	V
3 ..	0 ~ 5	V
4 ..	0 ~ 10	V
5 ..	Others	
Process Connection		
1 ..	1/2" PT	
2 ..	3/8" PF	
3 ..	Others	
Seal Material		
B ..	Buna-N	
C ..	Neoprene	
D ..	Viton	
E ..	Fluorosilicone	
F ..	Ethylene Propylene	
Z ..	Others	
Referance		
A ..	Absolute	
G ..	Gauge	