


ORDERING INFORMATION



ORDERING INFORMATION

P	5	0	1	H		0	1	0	M	G	T	D
Model Name P501 : High accuracy (±0.25%)				Pressure Range Refer to pressure range code ▶ page 2				Pressure Unit M:Mpa B:bar P:psi K:kgf/cm² H:mmH ₂ O G:mmHg T:torr		Process Connection A :PT 1/2" B :PT 3/4" C :PT 1" D :DIN 11851 E :Extended F :Flange I : IDF S : SMS T : Tri Clamp O : Other		
Out Put A : 4Wire mV D : 4Wire 1~5V E : 3Wire 1~5V H : 2Wire 4~20mA								Pressure Type G:Gauge C:Compound V:Vacuum A:Absolute		Electric Connection D:DIN 43650		